

03500.01561



*[Signature]*  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of: )  
HIROYUKI SUGIYAMA ET AL. ) : Examiner: A. Tubgang  
Application No.: 09/912,340 ) : Group Art Unit: 3729  
Filed: July 26, 2001 ) : U.S. Patent No.: 6,834,423 B2  
For: METHOD OF MANUFACTURING A ) : Issued: December 28, 2004  
LIQUID DISCHARGE HEAD ) : July 29, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, Virginia 22313-1450

**ATTENTION: CERTIFICATES OF CORRECTION BRANCH**

REQUEST FOR CERTIFICATE OF CORRECTION  
UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency

08/01/2005 HALI11 00000136 6834423


D1 FC:1811

100.00 OP

should be charged and any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010. All correspondence should be directed to our address given below.

Respectfully submitted,

  
\_\_\_\_\_  
Attorney for Patentees  
Douglas W. Pinsky  
Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200  
DWP/lip  
DC\_MAIN 199058

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,834,423 B2

DATED : December 28, 2004

INVENTOR(S) : HIROYUKI SUGIYAMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 2

Line 59, "On" (second occurrence) should read --on--.

## COLUMN 14

Line 6, "the" (second occurrence) should be deleted.

Line 26, "the" (second occurrence) should be deleted.

## COLUMN 16

Line 56, "to" should read --the--.

## COLUMN 17

Line 17, "is become unnecessary" should read --is unnecessary,--.

Line 18, "to simplify" should read --thereby simplifying--.

Line 47, "the" (first occurrence) should be deleted.

## COLUMN 20

Line 49, "method" should read --the method--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,834,423 B2

No. of add'l. copies  
@ 30¢ per page

